

To: Hanson, Kristen[KHanson@ldftribe.com]
From: Egan, Robert
Sent: Fri 7/15/2016 7:28:56 PM
Subject: RE: Recent Sampling Results , Haskell Lake Lodge 14277 State Highway 70W

Kristen,

Thank you for sending this out. I will call Gina to see if she has any questions.

Bob Egan

Corrective Action Manager

Underground Storage Tanks Section

RCRA Branch

EPA Region 5

(312) 886-6212

(312) 692-2911 (fax)

From: Hanson, Kristen [mailto:KHanson@ldftribe.com]
Sent: Friday, July 15, 2016 1:59 PM
To: giegan@co.vilas.wi.us
Cc: steveyach10@gmail.com; Christopher.Saari@wisconsin.gov; Egan, Robert
<egan.robert@epa.gov>
Subject: Recent Sampling Results , Haskell Lake Lodge 14277 State Highway 70W

Good Afternoon Gina,

Thank you for the call yesterday.

Attached is the last three sampling results for the Haskell Lake Lodge Property located at 14277 State Highway 70, Lac du Flambeau. The wells were sampled by an EPA contractor and the Tribe in response to private well concerns associated with the Haskell Lake Area Petroleum Contamination Site. The State refers to the contamination site as "Tower Standard".

Sampling in 2012, 2014, and 2015 found no detections of petroleum contaminants in the wells. The sheen that was witnessed in the bathroom toilet is likely iron or manganese. The iron problem was identified in the well soon after installation (see attached 1995 correspondence). The well was installed under the State Well Replacement Program after 2 previous wells were contaminated with petroleum originating from the neighboring property. I have not been successful in finding the state contact who dealt with the replacement program or any needed subsequent treatment.

The State WDNR assigned to the site is:

Chris Saari

Phone: (715) 685-2920

Christopher.Saari@Wi.gov

The EPA representative assigned to the site is:

Bob Egan

Corrective Action Manager

Underground Storage Tanks Section

RCRA Branch

EPA Region 5

(312) 886-6212

(312) 692-2911 (fax)

The two gentleman listed above were on the call yesterday.

I would expect that the bacteria problems are tied to the high iron concentrations. I understand that Mr. Yach has worked with Richardson Well Drilling to treat this well, but bacteria problems persist.

The Tribe resolves iron problems to this degree with either a treatment system or well replacement, when encountered on Tribal Lands.

Kristen Hanson

Environmental Specialist

Tribal Natural Resource Department

Lac du Flambeau Band of Lake Superior Chippewa Indians

Phone: (715)588-4290

Cell: (715)614-4644

